## Mail completed form to:

I. ACTION REQUESTED BY:

PUBLIC UTILITIES COMMISSION 500 EAST CAPITOL AVENUE PIERRE, SD 57501 ATTN: SOUTH DAKOTA ONE CALL BOARD OC03-010 RECEIVED

JUL 3 0 2003

SOUTH DAKOTA PUBLIC UTILITIES COMMISSION


## COMPLAINT

COMPLETE INFORMATION IS REQUIRED - ADDITIONAL PAGES MAY BE USED IF REQUIRED

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* X PERSON FILING COMPLAINT (Please print): MIKE JOHNSON PLANTINGR.
COMPANY (If applicable) SANTEL COMM. ADDRESS 308 So. Dumon'T PHONE NUMBER 605-796-4114
SIGNATURE OF COMPLAINTANT MATE DATE: 7-28-03 EMAIL ADDRESS: MICHALSON & SANTEL. NET
*If the complaint is files on behalf of a Company, the person signing this form should have the proper authority to file the complaint.
II. ACTION REQUESTED AGAINST:
NAME OF EXCAVATOR/FACILITY OPERATOR: DENN'S SCHULZ OF SULLZPHONE NUMBER: 605-928-3716 EIGCTRIC
ADDRESS: 704 WEST MAPLE ST. PARKSTON, S.D. 57366
WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO LOCATE TICKET #: START DATE ON TICKET:
DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? YES NO
WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES NO X
III. FACILITY INVOLVED (IF ANY)
TYPE OF FACILITY INVOLVED: TELEPHONE CABLE OPERATOR OF FACILITY (IF KNOWN): CENTRAL CABLE CONTRACTORS [WAUPUN], WISC 53963-9766 INSTALLING CABLE FOR SANTEL COMM. CO-OF IN PARKSTON. OPERATOR ADDRESS: W7435 COUNTY AW. WAUPUN; WISC PHONE NUMBER: 920-324-4/18  DEPTH OF COVER: 40"+ PRESSURE: VOLTAGE: NUMBER OF CABLE PAIRS: 400 CAPPER + TWO FOURTAGE PAIRS: 400 CAPPER + TWO FOURTAGE PAIRS: 400 CAPPER + TWO
IV. MARKING
WERE FACILITIES MARKED? YES_NO_X WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? YESNO_X_  DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YESNO_X  WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? YESNO_X  DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? YESNO_X
HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YESNO_X
IS THERE AGREEMENT? YES NO X IF NO, PLEASE EXPLAIN: HOME OWNER TOLD CONTRACTOR TO BILL HIM FOR ALL DAMAGES.
V. DAMAGE (IF ANY)
V. DAMAGE (IF ANY)


ADDITIONAL INFORMATION:
VI. PROBABLE VIOLATION
SPECIFIC STATUE(S) OR RULE(S) THAT WAS VIOLATED:  NO LOCATE CALLED IN TO ONE CALL
ADDRESS/LOCATION OF PROBABLE VIOLATION: LANDOWNER  EAST SIDE OF STREET FROM RUSS KABEISENAN RESIDENCE (PARKSTON) GAS-928-40
DATE/TIME OF PROBABLE VIOLATION _ THREE
DESCRIPTION OF PROBABLE VIOLATION: THIS IS NOT, THE FIRST TIME, SCHULT ELETRIC
HAS BEEN. DIGGING WITHOUT PROPER ONE-CALLS. BOTH UTILITIES
(telephone AND ELECTRIC) HAVE MENTIONED SUBJECTS LACK of
COMPLIANCE REGARDING JONTH DAKOTA ONE CALL LAWS. NO
MENTION of cut WAS MADE TO LANDOWNER OR CONTRACTOR
AFTER INCIDENT OCCURED.
* PHOTO SHOWS A GRAY PLASTIC PIPE (APP. 3"DIAMETER)
TRENCHED THRU A BLACK 400 PAIR CABLE AND TWO ORANGE
(4") DUCTS. ALL THREE WERE SEVERED AND COVERED UP.
Cut not DISCOVERED UNTIL 7-22-03 WHEN ROPE WAS
BEING PULLED HIRU DUCT.
·



PARKSTON, S.D.



PARKSTON, S.D.



PROPERTY OF SANTEL COMM. BOX 67 WOONSOCKET, S.D. AITN: MIKE JOHNSON

## TO WHOM IT MAY CONCERN:

PURSUANT TO THE COMPLAINT AGAINST DENNIS SCHULTZ, SCHULTZ ELECTRIC SERVICE, WITH REGARDS TO THE DIGGING / CUTTING OF TELEPHONE CABLE AND TWO PVC CONDUITS, I WOULD LIKE FOR IT TO BE KNOWN THAT I, RUSSELL KABEISEMAN TOLD MR. SHULTZ THAT THE AREA IN WHICH WE WOULD BE DIGGING WAS CLEAR OF ANY BURIED CABLES, WATER LINES, ETC. AS I HAD THE AREA CHECKED A YEAR PRIOR DURING CONSTRUCTION OF A BUILDING THAT I HAD ERECTED ON THE PROPERTY.

THE TELEPHONE COMPANY DID INSTALL NEW CABLES THIS SPRING, OF WHICH I THOUGHT WERE ON THE WEST SIDE OF THE STREET. DURING THEIR INSTALLATION WHEN REACHING THE NORTH EDGE OF MY PROPERTY ON THE WEST SIDE OF THE ROAD THEY THEN JUMPED TO THE EAST SIDE OF THE STREET AND CONTINUED TO INSTALL THE CABLES & CONDUIT TO THE SOUTH.

WHEN DIGGING THE TRENCH TO INSTALL MY CONDUIT WE WERE VERY CAREFUL NOT TO DAMAGE THE CABLES ON THE WEST SIDE OF THE STREET BUT WERE UNAWARE THAT THEY WERE ON THE EAST SIDE OF THE STREET THEREFORE CAUSING THE DAMAGE.

SINCERELY,

RUSSELL A. KABEISEMAN 511 E. ASH PARKSTON, SOUTH DAKOTA

## **SCHULZ ELECTRIC SERVICE**

Dennis Schulz 401 N. Chapman Dr. Parkston, SD 57366

Phone 1 605 928 3716 Fax 1 605 928 3206

September 05, 2003

SOUTH DAKOTA ONE CALL NOTIFICATION BOARD 1012 NORTH SYCAMORE AVE. SIOUX FALLS, SD 57110

To Whom It May Concern:

I was asked by Russ Kabeiseman to trench across the city street by his property. I had asked Russ if he was going to get the locates. He then said "everything was clear." The day of trenching the line across the city street, May 30th, I again asked if everything was clear. He said "yes everything was cleared and ready to go." The location of Russ Kabeiseman's property is 511 East Ash Street, Parkston, S. D.

Russ Kabeiseman is accepting all responsibility in this matter. I hope his letter will resolve this oversight.

In regards to the comment made in a letter received from you: 'This is not the first time Schulz Electric has been digging without properly notifying underground facility operators of excavation by notifying South Dakota One Call. Both utilities (telephone and electric) have mentioned Schulz Electric's lack of compliance regarding South Dakota One Call Statutes and Administrative Rules.' To my knowledge I have never cut a line. If you have this on record, please send a copy of date, time, and location of incident.

Sincerely,

Dennis Schulz/Owner/Electrical Contractor